

Product name: Lyo T4 DNA Ligase 50 U/ μ L

Catalogue reference(s): MB47301, 5000 U

Components	MB47301	Safety Information
Lyo T4 DNA Ligase	for 105 μ L	Not Hazardous *
T4 DNA Ligase Resuspension buffer	200 μ L	Not Hazardous *
4x Reaction Buffer for T4 DNA Ligase	600 μ L	Not Hazardous *

*The component mentioned above is not classified as hazardous according to CLP Regulation (EC) No 1272/2008. Consequently, does not require a Material Safety Data Sheet (MSDS), according to Regulation (EC) No 1907/2006, emended by Regulation (EC) No 2020/878.



Patrícia Ponte
Executive Direction